



RDMS DocID 00100874

39 Riverside Avenue  
Westport, Connecticut 06880  
(203) 227-8497



**Industrial Pollution Control, Inc.**

April 11, 1983

Ms. Cindy Gilder  
Solid Waste Management Branch  
EPA Region I  
JFK Building  
Boston, Mass.

RCRA RECORDS CENTER  
FACILITY MACDERMID  
I.D. NO. CTD001164599  
FILE LOC. R-18  
OTHER RDMS # 100874

Re: CTD 001164599  
MacDermid, Inc., Waterbury, Ct.

Dear Ms. Gilder:

Industrial Pollution Control is writing to you on behalf of our client, MacDermid, Inc. of Waterbury, regarding the nature of the sludge which is generated by their waste treatment plant.

Initially MacDermid submitted a Part A for this sludge on the assumption that chrome content and reactivity might cause this sludge to be a hazardous waste.

More recently, IPC has run EP Toxicity and Reactivity tests on the sludge to determine more specifically the characteristics of the sludge (IPC Report "Hazardous Waste Characteristics - Filter Press Sludge" dated 25 January 1982.)

These test show:

- chrome is well below allowable limits and other metals are not significant and, consequently, it is not EP Toxic
- the material is not reactive
- subsequent tests show that cyanide is not present

All of this material is sent off site within 90 days.

Therefore, since these tests show that these wastes are not hazardous, we request that MacDermids Part A be sent back to them and that they be removed from the system.

Thank you for your consideration.

Very truly yours,



Kenneth Lanouette, P.E.  
President

KL:sjm  
encl:

c.c. Mr. George Dews  
Hazardous Waste Section, DEP  
State Office Building  
165 Capital Ave.  
Hartford, Ct. 06106

Mr. Ray Koehler  
MacDermid, Inc.  
526 Huntingdon Ave.  
Waterbury, Ct. 06708

APR 14 1983